

**NUMBER:** 08-059-16 REV. A

**GROUP:** Electrical

**DATE:** July 14, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-059-16, DATED MAY 24, 2016, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH \*\*ASTERISKS\*\* AND INCLUDE 2014 MODEL YEAR AND A NEW LOP.

# SUBJECT:

Flash: Instrument Panel Cluster (IPC) Enhancement

## **OVERVIEW:**

This bulletin involves updating the IPC with the latest available software.

### **MODELS:**

\*\*2014\*\* - (WK) Jeep Grand Cherokee 2015

NOTE: This bulletin applies to vehicles within the following markets/countries: EMEA (Middle East Only).

NOTE: This bulletin applies to vehicles equipped with Middle East Equipment Group (Sales Code ABD) equipped with Navigation-capable radios (Sales Codes RJ3 or RJ4).

NOTE: This bulletin applies to vehicles equipped with Premium Instrument Cluster W/Tach (Sales Code JAJ) or equipped with Instrument Cluster W/Perf Display Screen (Sales Code JAV).

#### SYMPTOM/CONDITION:

Customers may experience the cluster displays English when requesting Arabic language is selected through a navigation-capable radio.

## **DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

### REPAIR PROCEDURE:

NOTE: The IPC Electronic Control Unit (ECU) has a long flash reprogramming completion time. Please verify the following on your Personal Computer (PC) before attempting to update this ECU. PC must be running on AC power supply only. PC hard drive must NOT be set to turn off in a period of time. PC must NOT be scheduled to go into sleep or standby mode. PC screen saver must be turned off. PC monitor must NOT be set to turn off in a period of time.

NOTE: Please verify that the vehicle battery is in a fully charged state and that a battery charger is connected during the entire flash reprogramming process.

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

- Reprogram the IPC with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
- 2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

# **POLICY:**

Reimbursable within the provisions of the warranty.

## TIME ALLOWANCE:

| Labor Operation No: | Description | Skill Category                     | Amount     |
|---------------------|-------------|------------------------------------|------------|
|                     | l '         | 6 - Electrical and<br>Body Systems | 2.0 Hrs.** |

NOTE: The expected completion time for the flash download portion of this procedure is approximately 100 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

## **FAILURE CODE:**

The dealer must choose which failure code to use. If the customer came in with an issue and if the dealer finds a software update to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

| CC | Customer Concern |
|----|------------------|
| RF | Routine Flash    |