



**NUMBER:** 08-080-13

**GROUP:** Electrical

**DATE:** October 11, 2013

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.*

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-077. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**

Radio Compass Function Inoperable

**OVERVIEW:**

This Bulletin involves replacing the Rear View Mirror.

**MODELS:**

2014 (WK) Grand Cherokee (International Only)

**NOTE: This bulletin applies to vehicles with Auto High Beam Headlamp Control (sales code LMS) built on or before June 03, 2013 (MDH 0603XX).**

**SYMPTOM/CONDITION:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68110891AD	Mirror, Rear View

**REPAIR PROCEDURE:**

1. Replace the rear view mirror by follow the detailed procedure in DealerCONNECT/TechCONNECT 23 - Body - Interior > MIRROR, Rearview > Removal/Installation.

**NOTE: Perform the Smartbeam System Calibration Procedure, (Refer to 08 - Electrical/8L > Lamps and Lighting/Lamps/Lighting > Exterior/SMART BEAM > Standard Procedure) .**

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
23-12-10- 02	Mirror, Inside Rear View - Replace (1 - Semi- Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------